

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
**NEW MEXICO OIL CONSERVATION COMMISSION**  
**JAN 8 1971**

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

**O. O. O.**  
**ARTESIA, OFFICE**

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator John A. Yates	8. Farm or Lease Name Jean M
3. Address of Operator 207 South 4th Street - Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>16S</u> RANGE <u>27E</u> NMPM.	10. Field and Pool, or Wildcat Riverside Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3313' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows:

Loaded hole with mud, cut off tubing at 7803' and 4½" casing at 5968'.

Spotted cement plugs as follows:

25 sacks 7803' - Top of tubing stub.  
 35 sacks 5968' - Top of 4½" casing stub.  
 35 sacks 2420-2320'  
 35 sacks 1350-1250'  
 35 sacks 850-750'  
 15 sacks 50' - Surface with Dry hole marker.  
 Heavy mud placed between each plug.

Cleaned location and it is now ready for inspection.

*revised*  
*11-8-74*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Eddy L. Hayes</u>	TITLE <u>Engineer</u>	DATE <u>1-7-71</u>
APPROVED BY <u>John M. Harris</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>NOV 4 1974</u>
CONDITIONS OF APPROVAL, IF ANY:		