

(10-7-76)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

PERMIT IN TRANSMITTANCE
(Other instructions on reverse side)

Copy to SE

Form Approved
Subject: PERMIT TO DRILL

6. LEASE DESIGNATION AND SURVEY NO.

NY-063578

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

9. FARM OR LEASE NAME

Federal

10. WELL NO.

1-30

11. FIELD AND POOL, OR WILSON

E. Redlake Creek-Skyline

12. SEC. T. R. W. OR BLM
SURVEY OR AREA

Sec 34, T16-S. 2-R20E

13. COUNTY OF INDIAN 14. STATE

Edw

New York

NOTICE AND REPORTS ON WELLS
(This form is to be used for notice to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF COMPANY ☐ OTHER

2. COMPANY ADDRESS

Union Production Company

3. COMPANY CITY AND STATE

1000 N. Central Expwy, Dallas, TX. 75206

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
Give as much detail as possible.)

1428' PHL & 2310' FWL

15. ELEVATIONS (Show whether on, at, or, etc.)

15. ELEVATIONS (Show whether on, at, or, etc.)

3570' GL

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

16. NATURE OF NOTICE OR INTENTION TO:

WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER TREATMENT ☐

MULTIPLE COMPLETS ☐

WATER ENLARGED ☐

ABANDON* ☐

WATER WELLS ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) Plugging ☐

(Note: Report results of multiple completion or well
Completion or Recompletion Report and Log form.)

17. IN CASE OF COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting and
completion of work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was plugged & abandoned as follows:

- 1-28-77 Moved in & rigged up. Stripped out rods & tubing.
- 1-30-77 Ran tubing & pumped 50 sx cement across perfs; 1428-1472'. WOC.
Re-ran tubing, did not tag plug. Pumped 50 sx cement across perfs. WOC.
Re-ran tubing & tagged plug @ 1100'. Circulated hole w/jell mud. Set 10 sx
plug @ surface.
- Set Dry hole marker - 2-3-77.

18. I HEREBY CERTIFY that the foregoing is true and correct

Don R. Collins

TITLE Operations Assistant

Drig & Prodn

DATE 2/1/77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

APPROVAL, IF ANY:

POD
1-10-77
4-1-77