m 3160-5 ovember 1983) ormeily 9-331) BUREAU OF LAND M	HE INTERIOR verge side)	UUTIONS ON 5. LEA	Budget Bureau No. 1 Expires August 31. 1 ISE DESIGNATION AND B LC 063578	985
SUNDRY NOTICES AND I (Do not use this form for proposals to drill or to Use "APPLICATION FOR PERM	REPORTS ON WELLS	PCEIVED	NDIAN, ALLOTTEE OR T	RIBE NAME
		7. UNI	T AGREEMENT NAME	
NAME OF OPERATOR	/ AU		M OB LEASE NAME	<u> </u>
Kincaid & Watson Drilling Company		D. C. D.	uthern Union F . MO.	ederal
P.O. Box 498, Artesia, New Mexico LOCATION OF WELL (Report location clearly and in accor See also apace 17 below.) At surface	88211-0498 ARTE	SIA, OFFICE	3 ELD AND POOL, OR WILD 1 Lake Queen-(-
660'/South, 1980'/East Section 34-16S 28E, Eddy County,	New Mexico	11. 38	C., T., B., M., OB BLK. AN BURVBY OR AREA 4-165-28E	
PEILMIT NO.	Show whether DF. RT. GR. etc.) 3555 GR		Eddy New	Mexico
Check Appropriate Box 1 NOTICE OF INTENTION TO:	To Indicate Nature of Notice	e, Report, or Other Do BUBBEQUENT REP		
TEST WATER SHUT-OFF PULL OR ALTER CAS FRACTURE TREAT MULTIPLE COMPLET SHOOT OR ACIDIZE ABANDON® REPAIR WELL CHANGE PLANS (Other) OFFICE OFFICE OFFICETED OFFICATIONS (Clearly S proposed work. If well is directionally drilled, give nent to this work.)®	E FRACTUBE SHOOTING (Other)	TREATMENT OR ACIDIZING	port and Log form.) g estimated date of at	arting any
We plugged this well as follows 25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se Set dry hole marker.	tween plugs.		Auc Auc Are	REC
25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se	tween plugs. eeded location.	: 	22	RECEIVED
25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se	tween plugs.	· · · · · · · · · · · · · · · · · · ·	80. 11 72	RECEIVED
25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se	tween plugs. eeded location.		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RECEIVED
<pre>25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se Set dry hole marker.</pre>	tween plugs. eeded location.		22 10 10 10 10 10 10 10 10 10 10 10 10 10	RECEIVED
<pre>25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-so Set dry hole marker.</pre>	tween plugs. eeded location.		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RECEIVED
<pre>25 sacks cement 1760-1639 50 sacks cement 620-460 set plug 30' to surface Loaded hole with jelled mud bet Cleaned up, ripped up and re-se Set dry hole marker.</pre>	tween plugs. eeded location.	ceasurer I	22 10 10 10 10 10 10 10 10 10 10 10 10 10	RECEIVED

...

Accretion up to explore the second se