

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
APR 25 1977
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. B-2178-4	
7. Unit Agreement Name	
8. Farm or Lease Name Kemper Delhi State	
9. Well No. 1	
10. Field and Pool, or Wildcat East Red Lake	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Kincaid & Watson Drilling Company
3. Address of Operator P.O. Box 498, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER C 540 FEET FROM THE North LINE AND 2994 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 17S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We sat a Bridge Plug at 1500'
 Dumped three bailers of cement on top of bridge plug,
 Circulated hole with mud, shot 7" at 600'
 Pulled 600' of 7" casing
 Pulled 529' of 8 5/8" casing
 Set cement plug at 600' 35 sacks
 Set cement plug at 250' 50 sacks
 Set cement plug at surface 10 ~~XXXX~~ sacks
 Set dry hole marker and cleaned up locations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy King TITLE Assistant Secretary DATE April 22, 1977
 APPROVED BY Dolan Thomas TITLE OIL AND GAS INSPECTOR DATE JUN 17 1977
 CONDITIONS OF APPROVAL, IF ANY: