

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TR. CASE\*  
(Other instructions on re-  
verse side)

copy to SF

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-012897

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Southern Union Production Company

3. ADDRESS OF OPERATOR  
Suite 1700, 8350 North Central Expressway, Dallas, TX 75206

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
990' FNL & 990' FWL

RECEIVED

MAR 29 1977

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Red Lake Queen Grayburg East

11. SEC., T., R., M., OR BLE. AND  
SURVEY OR AREA  
Sec 3, T-17S, R-28E

12. COUNTY OR PARISH  
Eddy

13. STATE  
New Mexico

14. PERMIT NO.  
15. ELEVATIONS (Show whether DT, RT, GR, etc.)  
3548 GL

O.C.C.

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

We propose to plug and abandon this well as follows:

1. A cement plug will be set across the perforations in the producing zone (Top 1374; Bottom 1414).
2. A cement plug will be set at surface and a dry hole marker will be installed.
3. All surface equipment will be removed and the location will be cleaned-up.

RECEIVED

SEP 13 1976

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Dan R. Collier*  
Dan R. Collier

TITLE

Operations Asst.

DATE

9/10/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side