

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-133100

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

2029-21

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Hanson Energy

3. Address of Operator

R.342 S. Haldeman Rd. Artesia NM 88210

7. Lease Name or Unit Agreement Name

State

8. Well No.

1

9. Pool name or Wildcat

Vandergriff Keyes Queen

4. Well Location

Unit Letter P : 330 Feet From The S. Line and 660 Feet From The E Li

Section 4

Township

17S

Range

28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3521 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB ☐


OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6 5/8 set at 1240'. Open hole from TD 1370. Will set Cement Plug from TD to 1190. Tag Plug. Fill with Gelled fresh water to 700' set plug from 700 to 500'. Fill w/ Gelled water to surface Set 50 foot plug. Set marker and clean location. Work will proceed as soon as Equipment is available.

* Perforate 6 5/8" casing to 900. Squeeze 100 cement Plug inside + outside 6 5/8" casing. TAG.

* Perforate 6 5/8" casing to 50'. Circulate cement to surface inside + outside 6 5/8" casing.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dalton Bell TITLE Agent DATE 11-27-00

TYPE OR PRINT NAME Dalton Bell TELEPHONE NO. 748-2134

(This space for State Use)

* Notice NM O.C.D. to witness plugging operations

APPROVED BY Mina Stillfield TITLE Field Rep II DATE 11/30/2000