

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

015F
Op +

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name Pandel State
--

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
--

8. Well No. 1

2. Name of Operator
American Exploration Company

9. Pool name or Wildcat Vandagriff Keyes

3. Address of Operator
2100 RepublicBank Center, Houston, Texas 77002

4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

* 25x5x4 Tag plug
MIRU Pulling Unit. POH w/production equipment. TIH w/tubing and circ. one hole volume of 9.6 ppg mud. Set two ~~100'~~ cement plugs with 50' above and below the casing shoes at depths of 1313' (5-1/2" csg. shoe), and 426' (10-3/4" surf. csg. shoe). Set 50' cement plug at surface up to 4'. Cut off casing tops @ 4'. Fill hole and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Marty B. McClanahan TITLE Sr. Production Analyst DATE 6/21/89
TYPE OR PRINT NAME Marty B. McClanahan TELEPHONE NO.

(This space for State Use) * As noted above
APPROVED BY Johnny Robinson TITLE OIL AND GAS INSPECTOR DATE 6-28-89
CONDITIONS OF APPROVAL, IF ANY: