

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088


WELL API NO.	15-030-133100
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2179
7. Lease Name or Unit Agreement Name	
Keyes State	
8. Well No.	2
9. Pool name or Wildcat	Red Lake Q-G-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3521 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Hanson Energy /
3. Address of Operator R 342 S Haldeman Rd. Artesia, NM 88210	4. Well Location Unit Letter H : 1980 Feet From The N Line and 660 Feet From The E Line Section 9 Township 17S Range 28E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 2 3/8 Tubing to 1283' and pump 55 sacks. Tag Plug at 1063'.
Circulate Hole with Gelled Fresh Water. Shot Pipe at 401' and run
Tubing to 460' and pump 30 Sack Plug. Tagged at 315'. Shot at 55' and
pumped 10 sacks. Circulated approx. 2 sacks to pit. Set 4 1/2 Marker.
Start cleanup. Will notify when ready for final inspection. OCD was
Notified at each Plug and Tag.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dalton Bell TITLE Agent DATE 10-4-01

TYPE OR PRINT NAME Dalton Bell TELEPHONE NO. 748-2134

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 10-23-01

CONDITIONS OF APPROVAL, IF ANY: