

11 Plugs Subject to Change

Operator Hansen Energy Phillips Balding St #2 TOPS
 Well Section 15 Township 17 Range 28
 Unit N
 API # 30-015-01369

Perf. 1592 all but Btm plug

Plug 60' 0" Surface.

Shoe Plug TAG
 ? 500'

Plug 1975' TAG

Bowers	~	988
Queen	~	1200
Grayburg	~	1650
San Antonio	~	1975

- * Contact OCD 24 hrs. prior to any work done.
- * Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- * Install dry hole marker as per Rule 202.B.2
- * Plugs are to be set from point indicated up.
- * Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- * Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- * Surface plug will be from 0' - 60'
- * Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists.
- * Plugs to be tagged will be indicated.

21