DEPARTMENT OF THE INTERIOR GEOLOGICAL JURVEY

18. Thereby certify that the foregoing is true and correct

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME Red Lake Premier Sand Unit. 8. FARM OR LFACE MAME Welch-Rold PL PSG 9. WELL NO. TR. 18 10. FIFT D OR WILL DOAT NAME
1. oil gas well other	
2. NAME OF OPERATOR Kersey & Company	
3. ADDRESS OF OPERATOR P.O. Box 316, Artesia, NM 88211-0316 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF [] [] FRACTURE TREAT [] [] SHOOT OR ACIDIZE [] [] REPAIR WELL [] [] MULTIPLE COMPLETE [] [] CHANGE ZONES [] [] ABANDON* [] (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 23.0 P.N., IL 50 P.E. SU/4 NE/4 Sec 20-17-29 N.M. 12. COUNTY OR PARISH 13. STATE Eddy NM 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) RECEIVED (NOTE: Report results of multiple completion or zone change on Farm \$10.3 1992 O. C. D. PIESIA OFFICE e all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
1. Spot 300 coment plug 1626-1 2. Perforate casing at 1200! 3. Place 100 coment plug in and 4. Perforate 7" casing at 600. 5. Place 100 coment plug in and 6. Surface plug and marker-50 in surface Lasing.	Lout of Casing:
Subsurface Safety Valve: Manu. and Type	Set @ Ft.