

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANTA FE               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | 1 |

RECEIVED  
OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501-16 '85

Form C-103  
Revised 10-1-78

O. C. D.  
ARTESIA, OFFICE

|                                                                                                      |
|------------------------------------------------------------------------------------------------------|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> For <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br>B-1969                                                               |
| 7. Unit Agreement No. Prem. 5d.<br>Red Lake Unit                                                     |
| 8. Farm or Lease Name<br>Paton Tr. 8                                                                 |
| 9. Well No.<br>1                                                                                     |
| 10. Field and Pool, or Wildcat<br>Red Lake                                                           |
| 12. County<br>Eddy                                                                                   |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                           |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Injection                                                                   |
| 2. Name of Operator<br>Kersey & Co.                                                                                                                       |
| 3. Address of Operator<br>Box 316, Artesia, N. Mex.                                                                                                       |
| 4. Location of Well<br>UNIT LETTER J 2310 1986 FEET FROM THE South LINE AND 2310 1986 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 28E N.M.P.M. |

|                                               |
|-----------------------------------------------|
| 15. Elevation (Show whether DF, RT, GR, etc.) |
|-----------------------------------------------|

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

|                                                |                                                      |
|------------------------------------------------|------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       |

SUBSEQUENT REPORT OF:

|                                                       |                                               |
|-------------------------------------------------------|-----------------------------------------------|
| REMEDIAL WORK <input type="checkbox"/>                | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPERATIONS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOBS <input type="checkbox"/>  | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 100' plug 1910-2010'
2. Cut and pull 4 1/2" casing @ 1650'
3. Set 100' plug in and out of stub, tag.
4. Set 100' plug 550-650 and tag.
5. Set surface plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Carey TITLE Partner DATE 10-16-85  
APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 22 1985  
CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness  
Plugging

10/10/10

10/10/10 10/10/10 10/10/10

10/10/10 10/10/10 10/10/10