

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dsf
lp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-01503
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1111
7. Lease Name or Unit Agreement Name <i>222nd State</i>
8. Well No. 3 SWD
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> SWD	2. Name of Operator MARBOB ENERGY CORPORATION
3. Address of Operator P.O. Drawer 227, Artesia, N.M. 88210	4. Well Location Unit Letter <u>6</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>17-S</u> Range <u>28-E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 35 sks cement plug @ 1975', W.O.C., tag cement top @ 1383'
- Load hole w/mud
- Perforate 4 1/2 casing and 7" @ 600', squeeze 25 sks cement, W.O.C., tag cement top @ 379', this plug covers the 8 5/8 shoe
- Perforate 4", 7" & 8 5/8 casing @ 60', circulate cement to surface between 4 1/2 & 7" csg and 7" & 8 5/8 csg. and 8 5/8 & open hole, total cement 45 sks

WORK COMPLETED 3/8/95

RECEIVED

MAR 21 1995

OIL CON. DIV.
DIST. 2

Post ID-2
4-7-95
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 3-8-95

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Ray Smith TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 4 1995