

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
 NEW MEXICO OIL CONSERVATION COMMISSION  
**AUG 9 1979**  
**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9434
7. Unit Agreement Name
8. Farm or Lease Name Humble "23"
9. Well No. 1
10. Field and Pool, or Wildcat Red Lake
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Kincaid & Watson Drilling Company
3. Address of Operator P.O. Box 498, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We plugged this well as follows:

25 sacks cement @ 2180'  
 Pulled 1027' 5 1/2" casing  
 80 sacks cement @ 1040' tagged plug at 790'.  
 35 sacks cement @ 485'-550' would not circulate.  
 Pumped 60 sacks cement on fluid at 120'  
 Tagged plug at 450'  
 Filled hole from 450' (with 8 yards of Ready Mix) to surface  
 Installed Dry Hole marker and cleaned up location.

*Old records show 8 3/8" - 502.505x  
 when well was plugged found only  
 10' of 8 3/8" at surface,*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy King TITLE Secretary Treasurer DATE August 8, 1979

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: