

ALL INFORMATION RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

OCT 27 1982

O. C. D.

ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. 647
7. Unit Agreement Name E.A. Press. Maint. Project
8. Farm or Lease Name Empire Abo Unit "B"
9. Well No. 39
10. Field and Pool or Wildcat SWD Paddock Empire Abo
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- **SWDW**

Name of Operator
RCO Oil and Gas Company, Division of Atlantic Richfield Company ✓

Address of Operator
P. O. Box 1710, Hobbs, New Mexico 88240

Location of Well
UNIT LETTER **G** **2310** FEET FROM THE ~~South~~ ^{North} LINE AND **1980** FEET FROM
East **26** TOWNSHIP **17S** RANGE **28E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3664' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

rigged up on 10/11/82. Installed BOP. Rel pkr & POH. Drld & CO to 6223'. Set cmt retr @ 6073'. Cmt qzd Abo perfs 6127-6220' w/200 sx C1"C" cmt on vac. Cleared cmt, WOC 4 hrs. Sqz cmtd thru retr 6073' w/150 sx C1"C". Final press. 1200#. Dumped 50' cmt on top of retr. Set pkr @ 3650', press annulus to 1000# for 30 mins. OK. POH w/pkr. Set cmt retr @ 3649'. Sqz cmt perfs 3809-4030' w/150 x C1"C" neat cmt. Final sqz press 1500#. Dumped 50' cmt on top of retr. Circ 10# brine wtr to 00'. Spot C1"C" cmt plug 900-600'. WOC. Tagged cmt plug w/tbg @ 578'. OK. Spot C1"C" cmt plug 56' to surf. Cut off wellhead below ground level. Install regulation dry hole marker. Clean and level location. P&A eff: 10/19/82. Final Report.

Post FD-2
11-5-82
P+P

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by Elizabeth S. Bush TITLE Drlg. Engr. DATE 10/21/82

by Ramsey Brooks TITLE Geologist DATE 3/17/83

CONDITIONS OF APPROVAL, IF ANY: