

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>B-2071  |
| 7. Lease Name or Unit Agreement Name<br>N G Phillips State  |
| 8. Well No.<br>5  |
| 9. Pool name or Wildcat<br>Artesia Queen Grbg SA  |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒

GAS WELL ☐

OTHER

RECEIVED

2. Name of Operator  
Marbob Energy Corporation

SEP 24 1991

3. Address of Operator  
P. O. Drawer 217, Artesia, NM 82810

O. C. D.

4. Well Location

ARTESIA OFFICE

Unit Letter J : 1650 Feet From The South Line and 1650 Feet From The East Line

Section 27 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3654' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon as follows: Set cmt plug from PBTD to 1950'. Tag plug @ 1970'. Set cmt plug 1600-1400' (Queen). Set cmt plug from 900-700' (Seven Rivers). Set cmt plug from 610-510' (Base 8 5/8" csg). Set surface plug and install dry hole marker and clean location.

1950

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robin Smith

TITLE Production Clerk

DATE 9/20/91

TYPE OR PRINT NAME Robin Smith

TELEPHONE NO. 748-3303

(This space for State Use)

APPROVED BY Johnny Robinson

TITLE OIL AND GAS INSPECTOR

DATE 10-1-91

CONDITIONS OF APPROVAL, IF ANY: