

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

O.C.D.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1111	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>injection</u>		7. Unit Agreement Name RLPSU Flood
2. Name of Operator <u>Kersey & Company</u>		8. Farm or Lease Name RLPSU-Tract 11
3. Address of Operator <u>P.O. Box 316, Artesia, NM 88211-0316</u>		9. Well No. <u>16</u> <u>Welch</u>
4. Location of Well UNIT LETTER <u>F</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.		10. Field and Pool, or Wildcat <u>RED Lake-Q-G-SA</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole with mud.
2. Spot cement plug 1994-1700'
3. Perforate at 600'.
4. Spot 100' plug in and out of casing.
5. Surface plug and marker.
6. Note 7" casing cemented with 100 sacks.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harold Kersey TITLE Co-Owner DATE 9-30-87

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE Oct 01 1987

CONDITIONS OF APPROVAL, IF ANY: