

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION
JAN 28 1972

O. C. C.
ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 647
7. Unit Agreement Name
8. Farm or Lease Name M. Yates
9. Well No. 3
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Atlantic Richfield Company ✓
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER P 330 FEET FROM THE South LINE AND 330 FEET FROM East THE LINE, SECTION 33 TOWNSHIP 17-S RANGE 28-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

Displaced 30 sx Class H cement in 7" casing to 1900'. Pld 300' of 8 1/4" casing. Shot 7" casing @ 715'. POH w/7" casing. Spotted 30 sx cement half in & half out of 7" stub @ 715'. Spotted 30 sx cement across 8 1/4" shoe @ 547'. Set 10 sk plug @ surface. Erected dry hole marker. Well P & A 1/22/72. 9#/gal gel mud left between all cement plugs.

Your office will be notified when location is ready for inspection.

csg. left in hole = 8 1/4" ~~300'~~ 300'-547'
7" from 715' - 200'S

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. L. Hatcher

TITLE Dist. Drlg. Supervisor

DATE 1/26/72

APPROVED BY [Signature]

TITLE OIL AND GAS INSPECTOR

DATE MAR 1 1972

CONDITIONS OF APPROVAL, IF ANY: