

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JAN 28 1972

C. C. C.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 647
7. Unit Agreement Name
8. Farm or Lease Name M. Yates
9. Well No. 4
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER J, 1650 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 17-S RANGE 28-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3656' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:
Displaced 30 sx cement in 7" casing to 1800'.
Shot off 7" casing @ 710'. Pulled 23 jts 7" casing. Spotted 30 sx cement half in & half out of 7" stub @ 710'. Spotted 30 sx cmt across 8 1/4" shoe @ 509'. Set 10 sk cement plug in 8 1/4" surface pipe. Erected dry hole marker. Well P & A 1/19/72. 9#/gal gel mud was left between all cement plugs. 8 1/4" casing remains intact.

Your office will be notified when location is ready for inspection.

*dry left hole 8 1/4" - 509
7" from 110 - 1892*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>R. D. Latches</i>	TITLE Dist. Drlg. Supervisor	DATE 1/26/72
APPROVED BY <i>[Signature]</i>	TITLE OIL AND GAS INSPECTOR	DATE MAR 2 1973

CONDITIONS OF APPROVAL, IF ANY: