

over perfs 695-715, Plug will be at 800-800, Perf csg at 500' and circ cnt inside and out 4 1/2" csg. Install dry hole marker. Clean location.