Submit 3 Copies to Appropriate District Office

1. Type of Well: AFT X

Name of Operator

3. Address of Operator

Well Location

Unit Letter _

PERFORM REMEDIAL WORK

work) SEE RULE 1103.

5/21/90

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER:

State of New Mexico

| ZI DP | |
|----------------|--|
| υψ | |
| Form C-103 | |
| Revised 1.1.29 | |

'15K

DISTRICT P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410

WELL

33

Energy, Minerals and Natural Resources Department OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30+015-01687 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATEKX MAY 24 '90 FEE 6 State Oil & Gas Lease No. 647 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) **077-89** EMPIRE ABO UNIT "F" & Well No. ARCO OIL AND GAS COMPANY 29 9. Pool same or Wildow BOX 1710, HOBBS, NEW MEXICO 88240 EMPIRE ABO E: 1980 Feet From The NORTH Line and 620 WEST Feet From The Line Township 17S thip 17S Range 28E

10. Elevation (Show whether DF, RKB, RT, GR, etc.) **EDDY NMPM** County 3674' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB TEMPORARILY ABANDON -OTHER: X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed TA & HOLD WELL BORE FOR FIELD BLOW DOWN TD 6150', PBD 5996' (BP), Perfs 5956-5978' MIRU. DDPU. RU hot oil unit pump 68. BPW down tubing. N/D W/H N/U BOP. Unset pkr POH w/tbg, SN & pkr. Tally out of hole RIH w/CIBP. Running tool, SN and tbg. Set CIBP. Circ hole w/8.6# brine w/WT 675 chemical. Pressure well up to 500 psi. Held for 20 mins. No loss in pressure. Chart attached. POH laying tbg down in singles. N/D BOP N/U W/H. Left one joint on W/H flange. SDON. CIBP set at 5930.15'. Pressure test witnessed by Johnny Robinson - NMOCD I hereby certify that the information above in true and complete to the best of my knowledge and belief. _ mma Administrative Supervisor DATE 5/23/90 TELEPHONE NO. 392-355]

- DATE

CONDITIONS OF APPROVAL, IF ANY:

James D.

8-2-90

TITLE

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

