

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

JUN 18 1991

WELL API NO. 30-015-01690
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "H"
8. Well No. 30
9. Pool name or Wildcat EMPIRE ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3668' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	4. Well Location Unit Letter N : 1980 Feet From The WEST Line and 660 Feet From The SOUTH Line Section 33 Township 17S Range 28E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6335'; PERFS: 6128-6136'

6/12/91 MIRU. DDP. N/D W/H. N/U BOP. POH w/TBG STRING. SDON.

6/13/91 RO. PICK UP CSG SCRAPER. RIH. POH w/SCRAPER & TBG. RIH w/CIBP & TBG. SET CIBP. POH w/2 JTS TBG. RU KILL TRUCK. CIRCULATE WELL TO TRANSPORT. CLOSE WELL IN. PRESSURE UP TO 500#. HELD FOR 15 MINS. NO LOSS OF PRESSURE. RD KILL TRUCK. POH w/TBG & CIBP RUNNING TOOL. SDON.

6/14/91 RO. LEFT 1 JT ON W/H FLANGE. ND BOP NU W/H. RDCL. CIBP SET @ 6116.29'. PRESSURE TEST CHART ATTACHED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 6/17/91
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 6/21/91
CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 6/96