

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C157
JP

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-01692
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Empire Abo Unit "F"
8. Well No. 31
9. Pool name or Wildcat Empire Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator ✓
ARCO Permian

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter **G** : **1980** Feet From The **N** Line and **2130** Feet From The **E** Line
Section **33** Township **17S** Range **28E** NMPM **Eddy** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6175' CR: 5868' PERFS: 5810-5860'

06/05/97: Set CIBP @ 6080'. Set CR @ 5868'. Squeeze abo perfs 5868-6080' w/100 sxs Class "C" neat. Perf abo interval 5810-5860' w/1-11/16" strip, 2 JSPF, 100 holes. Acidize w/1500 gals 15% NEFE acid w/500 SCF/bbl N2. Ran 120 ball sealers.

TD: 6175' CIBP @ 5802' PERFS: 5734-5796'

07/21/97: Set CIBP @ 5802'. Perf abo interval 5734-5796' w/1-11/16" strip, 2 JSPF, 62 holes. Acidize w/1500 gals 15% NEFE w/500 SCR/bbl N2. Ran 75 ball sealers. (OVER)



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 07/08/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY For Record Only TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

TD: 6175' CIBP: 5802' PERFS: 5734-5796'

98
02/13/96:

Frac down 2-7/8" tbg w/15,000 gals 20% Vis Pentol acid @ 12 BPM. 2-3/8" tbg set @ 5673'. Return well to production.