Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office <u>District I</u>	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-015-01698
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III	1220 South St. Francis Dr.		STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACKSTOA			Empire Abo Unit "E"
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM C-161)	FOR SUCH	
1. Type of Well:	/\$*	A 282	
Oil Well 🛛 Gas Well 🗌	Other ©	20 20	
2. Name of Operator		10 CC/ CO	8. Well No.
BP America Production C	ompany	49/50	E-31  9. Pool name or Wildcat
3. Address of Operator P.O. Box 1089 Eunice, NM	88231	108/2	Empire Abo Unit
4. Well Location			
T. Work Experience			
Unit Letter_B:_937_feet from the North_line and _1980_feet from the _Eastline			
Section 33	Township 17S Range 28		County Eddy
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ABANDONMENT
	COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
8/26/02 MIRUPU. 8/27/02 RIH w/ON-Off tool latched on to & POH w/ RBP. Cir. & cleaned hole.			
8/27/02 RIH w/ON-Off tool latched on to & POH w/ RBP. Cir. & cleaned hole. 8/28/02 Set WL 4 ½" CIBP @ 5818'. Filled hole w/ 9.5 salt gel mud. Pumped 25 sxs cmt on CIBP @ 5818'.			
8/29/02 Spotted 25 sxs cmt top of Glorieta,3422' to 3322'. Perf'd 4 ½ csg @ 1050', 4 ½ - 8 5/8" shoe.			
8/30/20 Sqz'd 50 sxs cmt @ 1050' to cover 4 ½ - 8 5/8 shoe. WOC. Did not tag TOC. RIH w/pkr set @ 600', pumped 50 sxs cmt			
w/2% calcium chloride.			
9/03/02 RIH tagged TOC @ 853'. Perf'd 4 ½ @590', Yates. Pumped 35 sxs cmt, 590' (Yates) to 490'. Perf'd 4 ½ csg @ 60'. Pumped 35 sxs cmt dn 4 ½", up 8 5/8" to surface and pit.			
9/07/02 Cut off wellhead and anchors 3'BGL. Clean up location. Set dry hole marker.			
570 7702 Cut on weimed and men	kits 5 DOD. Cloud up toution. 50	t dry more marier.	
1.4			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE // Nent Whitmin TITLE BURNING Muglist DATE 9/17/02			
SIGNATURE /// /ln/ (Nhumu TITLE /////AND J////// DATE 9////02			
Type or print name M Kent Whitmire Telephone No. 505-677-3642			
(This space for State use)	200	······································	2 012810114 2141 202 077 2012
/ Into spice for state ass,		A AA A	77 NOV 8 2002
APPPROVED BY DATE			
Conditions of approval, if any:	•	June 14	<i>P</i> (