

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Artesia, N. Mex., Aug. 10, 1934

Mr. **E. H. Wells**
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon Well
No. **1** in **W $\frac{1}{2}$ of NW** of Sec. **35** Twp. **17**, Rge. **28**,
N. M. P. M., **Artesia** Oil Field, **Eddy** County.
We plan to commence work on **August 15th,** 19**34**.

The reasons for wishing to abandon the well are as follows:

Non-productive.

The present condition of the well is as follows:

295 feet of 10" Casing.
592 feet of 8-1/4" Casing.
1100 feet of 6-5/8" Casing

DUPLICATE

The work which we propose to do in abandoning the well is as follows:

Fill hole with mud to 1900 feet. Cement with five sacks of cement.
Fill with mud to 1100 feet. Pull 6-5/8" casing. Fill with mud
to bottom of 8-1/4" casing. Pull 8-1/4" casing. Fill with mud to
bottom of 10" casing. Pull 10" casing and fill with mud to surface
and erect regulation marker.

Sincerely yours,

Approved **AUG 14 1934** 19.....

Except as follows:

WELCH BROTHERS

Company or Operator.

By **U. P. Welch**
Position **Partner**

Send communications regarding this well to

Name **Welch Brothers**
Address **Artesia, New Mexico**

State Geologist or Oil and Gas Inspector.