			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Submit 3 Copies to Appropriate District Office	State of New Energy, Minerals and Nat		artment Form C-103 Revised 1-1	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATION DIVISION 2040 Pacheco St.		WELL API NO.	
DISTRICT II Santa Fe, NM 87505 P.O. Drawer DD, Artesia, NM 88210		30 · 015 · 01734 5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X F 6. State Oil & Gas Lease No. 647	EE 🗆
SUNDRY NOTICES AND REPORTS ON WELLS			1 04 <i>1</i>	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Empire Abo Unit "G"	
1. Type of Well: OIL X GAS WELL \(\text{WELL} \)	OTHER	3 10 11 12 13 14 15 76		:
2. Name of Operator		√° / ?	Well No.	
BP America Production Compar	ly	D 2 2000	[∞] _37	I
3. Address of Operator	7	7 (UUZ	92 Pool name or Wildcat	
P.O. Box 1089 Eunice, NM 8	18231	NEUEIVED	Empire Abo	
4. Well Location Unit Letter L . 2310) Feet From The S	OCD - ARTESIA	o.♥/ w	
Unit Letter L : 2310	Feet From The	Line and 33	Feet From The W	Line
Section 35	Township 17S	tange 28E	NMPM Eddy	
Section 33	TOWNSHIP	ther DF, RKB, RT, GR, etc	141411	County
	<u>/////////////////////////////////////</u>	3685' DF		
11. Check A ₁	propriate Box to Indica	te Nature of Noti	ce, Report, or Other Data	
NOTICE OF IN	-	t e e e e e e e e e e e e e e e e e e e	SEQUENT REPORT OF:	
				_
PERFORM REMEDIAL WORK	PLUG AND ABANDON 📙	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONA	MENT
PULL OR ALTER CASING	OTHER TENTO	CASING TEST AND CE	П	WE111 —
POLE ON ALTER CASING —	П	CASING TEST AND CE	MENT JOB —	<u> </u>
OTHER:		OTHER:		
12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
TD: 6351' PBD: 6340'	PERFS: 6226-6238'			
08.07.87: Set CIBP @ 62	10'. Perfs: 6158-6168'			
08.11.87: Set CIBP @ 61 08.13.87: Set CIBP @ 60	50'. Perfs: 6118-6126'			
MIRUPU. NDWH. NUBOP. RIH w/pkr to PBD.				
Load & press test back s	ide of csa to 500#			
If hold, reset BP.				
If back side does not hold. Will move pkr uphole, find leak, and repair.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE JULIE N. M. M. MILE Sr. Administrative Assistant DATE 02.11.02				
TYPE OR PRINT NAME Kellie D. Mur	<u>rish</u>		TELEPHONE NO. 505,394	1.1649
(This space for State Use)				

_ TITLE .

Accepted for record

FEB 13 2002

APPROVED

CONDITION