

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-015-01734

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
647

7. Lease Name or Unit Agreement Name:
Empire Abo Unit "G"

8. Well No.
G-37

9. Pool name or Wildcat
Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-100) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
B-P America

3. Address of Operator
P.O. Box 1089 Eunice, New Mexico 88231

4. Well Location

Unit Letter L : 2310 feet from the South line and 330 feet from the West line

Section 35 Township 17S Range 28E NMPM Eddy County NM

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
KB 11'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. PROCEDURE TO P&A. NO UP HOLE POTENTIAL.

1. MIRU. NU BOP.
2. TIH & TAG. CIBP capped w/35' of cmt. @ 6059'.
3. Circulate hole w/9.5# salt gel mud.
4. PUH & spot 25 sxs. cmt. From 3870' -3770'.
5. Perf 5 1/2" csg. @ 770'.
6. TIH w/pkr. & squeeze 50 sxs. cmt. 770'-670'. 8 5/8" csg. shoe. TAG.
7. Perf 5 1/2" csg. @ 480'.
8. TIH w/pkr. & squeeze 35 sxs. cmt. 480'-380'. Covers Yates.
9. Perf 5 1/2" csg. @ 60'.
10. Circulate 5 1/2" & 8 5/8" csg. w/10 sxs. cmt. to surface.
11. Cut off well head & anchors 3' BGL. Clean up location. Set Dry Hole Marker.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Asst Admin Asst DATE 07.22.02

Type or print name Kellie D. Murrish
(This space for State use)

Telephone No. 505.394.1649

APPROVED BY [Signature] TITLE Wild Dept DATE JUL 30 2002

Conditions of approval, if any: