S. Outure 2 Courts T. A	\&\ \
Submit 3 Copies To Appropriate District Office State of New Mexico	C'A Form C-103
District I AAN England Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM, \$240	WELL API NO.
	30-015-01734
Digitica III	5. Indicate Type of Lease
District III 2002 Rio Brazos Rd., Aztec Olm 87410 FC 2012 1220 South St. Francis Dr.	STATE STATE
District IV ∞ OCD $AEVVED$ Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District III 1301 W. Grand Ave., Artesia NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 ECE/VED 1220 S. St. Francis Dr., Santa Fe, NM R7505 OL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	674
	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DETAL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Empire Abo Unit "G"
1. Type of Well:	
Oil Well 🛛 Gas Well 🗌 Other	
2. Name of Operator	8. Well No.
B-P America Production Co.	6 -37
3. Address of Operator	9. Pool name or Wildcat
P.O. Box 1089 Eunice, New Mexico	Abo
4. Well Location	700
Unit Letter L: 2310 feet from the SOUTH line and 330 feet from the WEST line	
ome botton B. 2510 feet from the 500111 line and 550 feet from the WES1 line	
Section 35 Township 17S Range 28E	ARADIA ELL C. ARA
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Eddy County NM
KB 11'	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: '	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. PLUG AND
DULL OF ALTER CARING TO ANY TIME	ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AI	ND 🗆
COMPLETION CEMENT JOB	
OTHER: OTHER:	[]
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or	
recompilation.	
9/6/02 Tagged CIBP @ 6024'. Filled hole w/9.5 salt gel mud. Spotted 25sxs cmt from 3870-3770'.	
0/0/00 Part 1 51/02 C 2702 C 1 50	
9/9/02 Perf'd 51/2" @ 770'. Squeezed 50 sxs cmt from 770-350', 85/8" csg shoe to 130' above the Yates Tagged TOC at 357'.	
Perf'd 51/2" @ 60'. Circulated 51/2" and 85/8" w/15 sxs cmt to surface.	
9/14/02 Cut off well head & anchors 3' BLG. Cleaned Location. Set dry hole marker.	
4	
ost Peth	
	
Š	
\mathcal{Z}_{s}	
I hereby certify that the information above is true and complete to the best of my knowledge	and beliefo
SIGNATURE TITLE (JEGA TONT DATE 9/16/02	
WAN I I A I I I	
Type or print name 1711. Kent Whitmire Telephone No. 505-677-3642	
(This space for State use)	
APPPROVED BYTITLE	JAN 14 2003
Conditions of approval, if any	W 2 UAND 14 2003
va uppavim, it mij.	F