

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
300150174000

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
647

7. Lease Name or Unit Agreement Name
EMPIRE ABO UNIT F

8. Well No.
40

9. Pool name or Wildcat
EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
ARCO OIL AND GAS COMPANY

3. Address of Operator
BOX 1710, HOBBS, NEW MEXICO 88240

4. Well Location
Unit Letter H : 1650 Feet From The NORTH
Section 35 Township 17S Range 28E Line and 990 Feet From The EAST Line

RECEIVED

APR 05 '89

O. C. D.
ARTESIA, OFFICE

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3671.2' GR NMPM EDDY County

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☒

PULL OR ALTER CASING ☐

OTHER: ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Procedure as follows:

- MIRU DDPU
- Shear standing valve
- RIH w/swab to clear tbg
- Install BOP & POH w/tbg & ACC
- RIH w/CIBP on tbg
- Set CIBP @ 6140' RKB
- POH w/l jt
- Pump 105 BBLS 8.6# brine w/2 gal WT 675/10 BF to establish circulation
- SI Rams on BOP & Press. Test to 500#. Install chart
- If csg holds, POH, laying tbg down. Leave 1 jt on flange
- If csg doesn't hold, get ahold of Eng. Dept. for further instructions
- RDCL. Close all tbg, csg, surface csg valves

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

NATURE Services Supervisor TITLE 4-3-89 DATE

Original Signed By Mike Williams TELEPHONE NO.

APPROVED BY: APR 10 1989 DATE

Notify Temporary Abandonment to witness