State of New Mexico Eners,, Ainerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I	OIL CONSERVATIO	MOISIVIC IA			
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION 2040 Pacheco St.		WELL API NO.		
DISTRICT	Santa Fe, NM 87505		30-015-02126		
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210			sIndicate Type of Lease		
DISTRICT III		#			FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		9- An 1	6State Oil & Gas Leas	se No.	
CHARDY MOTIOSO AND DEPORTS ON MELLO					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7Lease Name or Unit Agreement Name		
			Artesia Unit	Agreement Name	
	01) FOR SUCH PROPOSALS.)		- 71100/4 07/11		
¹Type of Well: OIL GAS	NAME AND A				į
WELL WELL	OTHER WIW		«Well No.		
2Name of Operator Melrose Operating Co.			20		
3Address of Operator			Pool name or Wildca		
PO Box 5061, Midland, TX 79704		<u></u>	Artesia QN-GB-	SA	
4Well Location	Feet From The South	tine and 330		East լ	
Unit Letter : 2310	Feet From TheSouth	Line and 330	Feet From The	Lust	ine
Section 35	Township 17S F	Range 28E	NMPM	Eddy Coun	ty
	10Elevation (Show whether DF,	RKB, RT, GR, etc.)			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBS			SEQUENT RE	PORT OF:	
DI LIC AND ARANDON				AL TERINO CARRIO	F1
PERFORM REMEDIAL WORK	PLOG AND ADARDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING C	OPNS.	PLUG AND ANBANDON	MENT X
ULL OR ALTER CASING CASING TEST AND CEM			ENT JOB		
OTHER:		OTHER:			
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
WAN, SEE NOTE 1166.					
6/21/00 -					
Notify OCD. Move equip to location. MI & RU. ND wellhead. NUBOP. Unset pkr. POH. RIH & set CIBP @ 2150' NH w/tbg. Load hole w/10# mud. Spot 40 sx @ 2150'. POH to 1150' & spot 25 sx. POH. Close in well.					
mud. Spot 40 sx @ 2130 . POH to 1130 & spot 23 sx. POH. Close III Well.					
6/22/00 -					
RIH & tag @ 690'. POH. Weld on pull nipple. Cut csg @ 690'. POH w/19 jts. RIH & spot 45 sx @ 748'. POH. WOC. RIH & tag @ 547'. POH & spot 20 sx @ 30' to surf. RD. Cut off wellhead. Level pit & cellar.					
Install dry hole marker.					
				Λ	2 - 1 3
				1	
I hereby certify that the information above jetrue and complete to the best of my knowledge and belief.					
I hereby certify that the information above by	<u></u>			07.00.00	
SIGNATURE DOMME	thuster 11	TLE Regulatory Tech.		DATE 07-20-00	
TYPE OR PRINT NAME Bonnie Atwater				TELEPHONE NO. 915/68	5-1761
(This space for State Use)		1 0			
B. D.	. —	1	7	O. V	Ω.Ω
APPROVED BY // My Jun	7 TI	TLE <u>JELD LEP</u>	<u>+</u>	DATE 7-26 -	
CONDITIONS OF APPROVAL, IF MY:		•			
•					