

LC-061638

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ (OTHER) Water Injection		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR General American Oil Company of Texas ✓		8. FARM OR LEASE NAME Brewer	
3. ADDRESS OF OPERATOR P. O. Box 128 Loco Hills, New Mexico 88255		9. WELL NO. 15	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL and 1977' FWL		10. FIELD AND POOL, OR WILDCAT High Lonesome	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T-16S, R-29E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3733' DF		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to abandon the above well as follows:

1. Spot 100' plug from 2090'-1990' to cover open hole section, 2090'-2060'.
2. Perforate 4 holes @ 975', Base of Salt, and squeeze 55 sacks cement into formation.
3. Perforate 4 holes @ 480', Top of Salt, and squeeze 55 sacks cement into formation.
4. Perforate 4 holes @ 350', water zone, and squeeze enough cement to circulate to surface.
5. Set 10 sack surface plug.
6. Erect permanent dry hole marker.



18. I hereby certify that the foregoing is true and correct

SIGNED M. L. LansingTITLE EngineerDATE June 29, 1981

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

JUL 1 1981

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side