

LC-067610-a

C/SF

RECEIVED BY

AUG 14 1981

## NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

O. C. D.

ARTESIA OFFICE

Water Injection

2. NAME OF OPERATOR

General American Oil Company of Texas

3. ADDRESS OF OPERATOR

P. O. Box 128 Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

990' FSL and 2310' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3704' DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bosworth

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

High Lonesome

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 14, T-16S, R-29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The following work was completed March 26 — 30, 1981.

1. Tubing and packer pulled.
2. Set 50 sack plug, 2059'-1803', (Open hole section 2059'-2029').
3. Determined no casing free.
4. Perforated 4 holes @ 870' and squeezed 55 sacks cement into Base of Salt, (Plug inside casing 920'-810').
5. Perforated 4 holes @ 455' and squeezed 110 sacks cement into Top of Salt and water zone, (Plug inside casing 505'-214').
6. Set 10 sack plug @ surface.
7. Permanent dry hole marker installed.

Post ID-2  
8-23-85  
P+A

Additional report will be submitted when the location is cleaned-up at the end of the 10 well abandonment program.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. S. Lansing

TITLE

Engineer

DATE

April 2, 1981

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-13-85

CONDITIONS OF APPROVAL, IF ANY: