Form 9-331 Dec. 1973

UNITED STATES

Drawer DD

Artesia, NM 88210

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC-061638
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME RECEIVED
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other Water Injection .	9. WELL NO.
2. NAME OF OPERATOR	#18 O. C. D.
General American Oil Company of Texas 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME RTESIA, OFFICE
P.O. Box 128 Loco Hills, New Mexico 88255	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 14, T-16S, R-29E
AT SURFACE: 1980' FSL and 1980' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15 FLEVATIONS (OLICIUS DE L'ORI
	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE FRACTURE TREAT FRACTURE	•
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
ABANDON* \(\sum \) (other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.)	eall pertinent details, and give pertinent dates rectionally drilled, give subsurface locations and to this work.)*
This well was plugged and abandoned as follow	
 1. 100' Plug was set from 2047'-1947' to cover 2. Perforated 4 holes @ 1027'. top of Yates and into formation. 	open hole section 2047'-2019'.
3. Perforated 4 holes @ 420', 25' above top of cement into formation.	salt, and squeezed 55 sacks of
4. Perforated 4 holes @ 350', water zone, and sometion.	squeezed 55 sacks of cement into
5. 10 sack plug was set at surface.)D))E(C)E)[/(V)E/D
6. Permanent well marker was erected.	My Carlo
7. Location, road was cleaned, ripped and re-se	eeded.
	AUG 2 7 1982
Subsurface Safety Valve: Manu. and Type	nfete@acFt
18. I hereby certify that the foregoing is true and correct	MINERALS MGMT. SERVICE
signed Sandell M. Hawkinstitle Superintender	
APPROVED his space for Federal or State offi	ce use)
APPROVED TITUE	DATE
MAR 9 1987	· red

JAMES A. GILLHAN-See lestructions on Reverse Side

DISTRICT SUPERVISOR