			COPY					
Herm 4-511 UNITE STATES SUBMIT IN TRIPLIC MAN 1000 F THE INTERIOR SUBMIT IN TRIPLIC CODE F DESTRUCTION OF THE INTERIOR SUBMIT IN TRIPLIC					• • • • • • • • • • • • • • • • • • • •	 Form approved Budget Bureau No. 42 R1424 DELEASE DESIGNATION AND BERIAL NO. 		
112CEN		GEOLOGICAL S		AV ANTAL RIGHT	1	LC-061638	c/s	
i Do not	use this form for pro-	TICES AND R	EPORTS O	k to a different reservoir.		INDIAN, ALLOTTEE OR 1	BIRE NAME	
	A, OFFICE		•		7. ()	NIT AGREEMENT NAME		
NAME OF OP	WELL OTHER	Water Inject	.10n		8. 54	ARM OR LEASE NAME		
General American Oil Company of Texas						Brewer		
P. O. Box 128 Loco Hills, New Mexico 88255						ыл. ко. 2]		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 helow.)						10. FIELD AND POOL, OR WILDCAT		
660' FNL and 660' FWL						High Lonesome		
, c		OOU FWL			11. 1	EC., T., R., M., OR BEK. A SURVEY OR AREA	ND	
						. 14, T-16S, F		
4. PERMIT NO.		15. ELEVATIONS (S 3711		T, GR, etc.}		Eddy New	Mexico	
5.	Check A	Appropriate Box To	o Indicate Na	ture of Notice, Report,	, or Other I	Data		
	NOTICE OF INT	ENTION TO:	, _	я	UBREQUENT RI	EPORT OF:		
	R SHUT-OFF	PULL OR ALTER CAST	NG	WATER SHUT OFF		REPAIRING WELL		
FRACTURE 1 SHOOT OR A		MULTIPLE COMPLETE ABANDON®		FRACTURE TREATMENT SHOOTING OR ACIDIZIN	6	ALTERING CABING ABANDON MENT [®]	XX	
REPAIR WEI	L1.	CHANGE PLANS		(Other)	·	-	_	
			15'. (Open	— 7, 1981: hole section 20	022'-199	1').		
	Perforated 4	holes @ 825'	(Base of	Salt) and squeez ng 875'-705').	zed 55 sa	acks cement		
4.	Perforated 4	holes @ 420' o formation.	(Top of S	alt and water zo rculated to surf	one) and Face, (p	squeezed 95 s lug inside cas	acks ing	
5.	Set 10 sack surface plug.							
6.	Installed pe	rmanent dry h	ole marker	•				
	Additional re of the 10 we	eport will be ll abandonmen	submitted t program.	when location i	is cleane	ed up at the e	nd	
3. I hereby cer	tify that the foregoing		·			.	_	
	V // ·	sec.	TITLI: Engi	neer		DATE April 8,	1981	
SIGNED	m. 8. 8a	0						