

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Cons.
N.M. Div-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993
Lease Designation and Serial No.

C191

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Water Injection Well

2. Name of Operator
Vintage Drilling LLC

3. Address and Telephone No.
P.O. Box 158, Loco Hills NM 88255 505-746-1669

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)
2310' FSL and 2310' FEL
Sec 15, T16S, R29E

NM 5523
6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
High Lonesome Penrose Unit #5

9. API Well No.
30-015-02721

10. Field and Pool, or Exploratory Area
High Lonesome Queen

11. County or Parish, State
Eddy County, NM

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plug 1900' - 2020'

*Perforate @ 875' & set solid plug 775' - 875' Tag.

*Perforate @ 470' & set solid plug 370' - 470' Tag.

0-50' surface plug

Install dry hole marker

*Perforate means to perforate & squeeze w/sufficient cement (+/- 40 sks) to have a solid plug outside & inside the casing. Surface casing shoe plugs should have enough cement to circulate to the surface in the annulus between the 8 5/8" surface casing & the production casing.

8 5/8" 17# 420' W/75 sks

4 1/2" 9# 2020' W/100 sks

Perforations 1957' - 1969' T.D. 2020'

Accepted for Record
2-27-02

14. I hereby certify that the foregoing is true and correct

Signed *Marie Durham*

Title Marie Durham

Date 2/15/02

(This space for Federal or State office use)

Approved by (ORIG. SGD) DAVID R. GLASS

Title

Date

FEB 19 2002

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Title 18 U.S.C Section 1001. makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representation & as to any matter within its jurisdiction

DAVID R. GLASS
PETROLEUM ENGINEER

• See Instruction on Reverse Side