

Form 201  
May 1965

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL  
COPY TO: DISTRICT OFFICE  
VERSUS 8100

TE  
FO

FORM 201-100  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-068677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such purposes.)

RECEIVED BY

JUL 22 1986

O. C. D.

ARTESIA, OFFICE

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection

2. NAME OF OPERATOR Aceco Petroleum Company 505-746-6156 or 746-2676

3. ADDRESS OF OPERATOR 2106 W. Richey, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1310' FNL & 2630' FWL of Section 15, T16S, R29E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3707'

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Davis Federal

9. WELL NO.

#11

10. FIELD AND POOL, OR WILDCAT

High Lonesome Queen

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 15, T16S, R29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give sub-surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

NOTE: The NMOCD requires this injection well to be plugged and abandoned as it did not pass the pressure test. We plan to set the following plugs, subject to approval:

- 1) Spot 35 Sxs. of Class "C" Cement from T.D. of 2001' to 1875'. This plug will take the place of a cast iron bridge plug in order to isolate the perforations. Will tag 50' above top perforation.
- 2) Tag top of plug after 2 hrs. Spot 25 Sxs. of Class "C" Cement from 1750' to 1650'. This plug will cover the Queen formation from the top.
- 3) Tag top of plug after 2 hrs. Spot 25 Sxs. of Class "C" Cement from 900' to 800'. This plug will isolate the base of the salt.
- 4) Tag top of plug after 2 hrs. Spot 25 Sxs. of Class "C" Cement from 450' to 350'. This plug will cover the top of the salt.
- 5) Tag top of plug after 2 hrs. Spot 50 Sxs. of Class "C" Cement from 250' to surface. This plug will cover the bottom of the 8 5/8" at 200' and also serve as surface plug.
- 6) Cut off all casing and anchors below surface; set P&A marker. Clean and level location.

18. I hereby certify that the foregoing is true and correct

SIGNED

his space for Federal or State office use)

PROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Secretary

DATE

7-16-86

TITLE


DATE

7-22-86

\*See Instructions on Reverse Side

Subject to  
Like Approval  
by State

Arco Petroleum Co.  
DAVIS Federal #11  
Plug & Abandon



Well Name: DAVIS Fed #11  
Field: High Lonesome Queen  
County: Eddy Co., N.M.  
Location: T-16 N. R. 2 E. N.M.P.M.  
Sec. 15 & 1310 - NL + 2630' FWL