

U. S. LAND OFFICE Roswell, N. M.
SERIAL NUMBER L.C. 062996 (t)
LEASE OR PERMIT TO PROSPECT

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LOG OF OIL OR GAS WELL

LOCATE WELL CORRECTLY

Company Charles A. Steen Address Box 1268 Artesia, New Mexico
 Lessor or Tract George Atkins Field High Lonesome State New Mexico
 Well No. 1 Sec. 17 T. 16 R. 29 Meridian _____ County El Paso
 Location 2310 ft. N of E Line and 330 ft. W of E Line of section 17 Elevation 3059

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Date July 22, 1950 Signed Robert T. Evans
Title Geologist

The summary on this page is for the condition of the well at above date.

Commenced drilling April 11, 1936, 19 Finished drilling May 14, 1936, 19

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

(Continue gas by G)

No. 1, from 1776	to 1308	No. 4, from	to
No. 2, from	to	No. 5, from	to
No. 3, from	to	No. 6, from	to

IMPORTANT WATER SANDS

No. 1, from 252 to 260 No. 3, from _____ to _____
No. 2, from 1560 to 1565 No. 4, from _____ to _____

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	
3 5/8	10V	used	490	tex.pat.					surface
5 1/2	10V	new	1025	floor					protection
2 1/4	10V	new	1025	floor					protection

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
3 5/8	490	100	pumped		
5 1/2	1825	100	pumped		

PLUGS AND ADAPTERS

Fishing plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

[illegible]

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
Cable tools were used from 0 feet to 1825 feet, and from _____ feet to _____ feet

DATES

-----, 19----- Put to producing ----- June 1 -----, 1953-----
The production for the first 24 hours was 45----- barrels of fluid of which 100% was oil; -----%
emulsion; -----% water; and -----% sediment. Gravity: °Bé 24-----

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

		EMPLOYEES
--	--	------------------

EMPLOYEES

EMPLOYEES		EMPLOYEES	
Y.A. [unclear]	, Driller	Y.A. [unclear]	, Driller
K. Hoover	, Driller	W.J. Clancy	, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
ELECTRIC LOG SUPPLIED			

COLYF LEE [OVER]

LENNER, G.

16-43094-3

WALTON RECORD-Continued

A blank sheet of graph paper with a grid pattern. The grid consists of 10 columns and 8 rows of squares. The lines are thin and black, set against a white background. There are no margins or additional markings on the page.

Apr 11 18, 1956
Apr 11 27, 1956
Apr 11 28, 1956
May 2, 1956
May 3, 1956
May 4, 1956
May 5, 1956
May 7, 1956
May 8, 1956
May 9, 1956
May 14, 1956
May 17, 1956
May 18, 1956
May 19, 1956
May 20, 1956
May 21, 1956
May 22, 1956
May 23, 1956
May 24, 1956
May 25, 1956
May 26, 1956
May 27, 1956
May 28, 1956
May 29, 1956
May 30, 1956
May 31, 1956
Jun 1, 1956
Jun 2, 1956
Jun 3, 1956
Jun 4, 1956
Jun 5, 1956
Jun 6, 1956
Jun 7, 1956
Jun 8, 1956
Jun 9, 1956
Jun 10, 1956
Jun 11, 1956
Jun 12, 1956
Jun 13, 1956
Jun 14, 1956
Jun 15, 1956
Jun 16, 1956
Jun 17, 1956
Jun 18, 1956
Jun 19, 1956
Jun 20, 1956
Jun 21, 1956
Jun 22, 1956
Jun 23, 1956
Jun 24, 1956
Jun 25, 1956
Jun 26, 1956
Jun 27, 1956
Jun 28, 1956
Jun 29, 1956
Jun 30, 1956
Jul 1, 1956
Jul 2, 1956
Jul 3, 1956
Jul 4, 1956
Jul 5, 1956
Jul 6, 1956
Jul 7, 1956
Jul 8, 1956
Jul 9, 1956
Jul 10, 1956
Jul 11, 1956
Jul 12, 1956
Jul 13, 1956
Jul 14, 1956
Jul 15, 1956
Jul 16, 1956
Jul 17, 1956
Jul 18, 1956
Jul 19, 1956
Jul 20, 1956
Jul 21, 1956
Jul 22, 1956
Jul 23, 1956
Jul 24, 1956
Jul 25, 1956
Jul 26, 1956
Jul 27, 1956
Jul 28, 1956
Jul 29, 1956
Jul 30, 1956
Aug 1, 1956
Aug 2, 1956
Aug 3, 1956
Aug 4, 1956
Aug 5, 1956
Aug 6, 1956
Aug 7, 1956
Aug 8, 1956
Aug 9, 1956
Aug 10, 1956
Aug 11, 1956
Aug 12, 1956
Aug 13, 1956
Aug 14, 1956
Aug 15, 1956
Aug 16, 1956
Aug 17, 1956
Aug 18, 1956
Aug 19, 1956
Aug 20, 1956
Aug 21, 1956
Aug 22, 1956
Aug 23, 1956
Aug 24, 1956
Aug 25, 1956
Aug 26, 1956
Aug 27, 1956
Aug 28, 1956
Aug 29, 1956
Aug 30, 1956
Sep 1, 1956
Sep 2, 1956
Sep 3, 1956
Sep 4, 1956
Sep 5, 1956
Sep 6, 1956
Sep 7, 1956
Sep 8, 1956
Sep 9, 1956
Sep 10, 1956
Sep 11, 1956
Sep 12, 1956
Sep 13, 1956
Sep 14, 1956
Sep 15, 1956
Sep 16, 1956
Sep 17, 1956
Sep 18, 1956
Sep 19, 1956
Sep 20, 1956
Sep 21, 1956
Sep 22, 1956
Sep 23, 1956
Sep 24, 1956
Sep 25, 1956
Sep 26, 1956
Sep 27, 1956
Sep 28, 1956
Sep 29, 1956
Sep 30, 1956
Oct 1, 1956
Oct 2, 1956
Oct 3, 1956
Oct 4, 1956
Oct 5, 1956
Oct 6, 1956
Oct 7, 1956
Oct 8, 1956
Oct 9, 1956
Oct 10, 1956
Oct 11, 1956
Oct 12, 1956
Oct 13, 1956
Oct 14, 1956
Oct 15, 1956
Oct 16, 1956
Oct 17, 1956
Oct 18, 1956
Oct 19, 1956
Oct 20, 1956
Oct 21, 1956
Oct 22, 1956
Oct 23, 1956
Oct 24, 1956
Oct 25, 1956
Oct 26, 1956
Oct 27, 1956
Oct 28, 1956
Oct 29, 1956
Oct 30, 1956
Nov 1, 1956
Nov 2, 1956
Nov 3, 1956
Nov 4, 1956
Nov 5, 1956
Nov 6, 1956
Nov 7, 1956
Nov 8, 1956
Nov 9, 1956
Nov 10, 1956
Nov 11, 1956
Nov 12, 1956
Nov 13, 1956
Nov 14, 1956
Nov 15, 1956
Nov 16, 1956
Nov 17, 1956
Nov 18, 1956
Nov 19, 1956
Nov 20, 1956
Nov 21, 1956
Nov 22, 1956
Nov 23, 1956
Nov 24, 1956
Nov 25, 1956
Nov 26, 1956
Nov 27, 1956
Nov 28, 1956
Nov 29, 1956
Nov 30, 1956
Dec 1, 1956
Dec 2, 1956
Dec 3, 1956
Dec 4, 1956
Dec 5, 1956
Dec 6, 1956
Dec 7, 1956
Dec 8, 1956
Dec 9, 1956
Dec 10, 1956
Dec 11, 1956
Dec 12, 1956
Dec 13, 1956
Dec 14, 1956
Dec 15, 1956
Dec 16, 1956
Dec 17, 1956
Dec 18, 1956
Dec 19, 1956
Dec 20, 1956
Dec 21, 1956
Dec 22, 1956
Dec 23, 1956
Dec 24, 1956
Dec 25, 1956
Dec 26, 1956
Dec 27, 1956
Dec 28, 1956
Dec 29, 1956
Dec 30, 1956
Dec 31, 1956

It is for the greatest importance to have a complete history of the well. Please state in detail the dates of refilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

U. S. GOVERNMENT PRINTING OFFICE 16-53084-2

FORMATION		TOTAL FEET		TO-	
1	1000	1000	1000	1000	1000
2	2000	2000	2000	2000	2000
3	3000	3000	3000	3000	3000
4	4000	4000	4000	4000	4000
5	5000	5000	5000	5000	5000
6	6000	6000	6000	6000	6000
7	7000	7000	7000	7000	7000
8	8000	8000	8000	8000	8000
9	9000	9000	9000	9000	9000
10	10000	10000	10000	10000	10000