

c19K

Form 3160-5
(August 1999)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 20001. Type of Well
☐ Oil Well ☐ Gas Well ☐ Other D&A well drilled in 19542. Name of Operator
Beach Exploration, Inc.3a. Address
800 N. Maricfield Ste. 200, Midland, TX 797013b. Phone No. (include area code)
915-683-62264. Location of Well (Footage, Sec., T., R., M., or Survey Description)
330' FSL 1650' FEL SEC-UNIT 17-O TWP 16S RNG 29E5. Lease Serial No.
NML046119A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
(George Atkins) Iles Fed. #59. API Well No.
30-015- 0275510. Field and Pool, or Exploratory Area
High Lonesome Queen11. County or Parish, State
Eddy

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal
			☐ Water Shut-Off
			☐ Well Integrity
			☐ Other
			Re-Plug

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 1 Remove dry hole marker
- 2 PU 6 3/4" bit, drill out surf plug and 270'-285' plug
- 3 Wash down to cmt plug at 1554'
- 4 Circulate hole w/10ppg mud, POOH
- 5 RIH open ended to 1554' and pump 36sx cmt plug (bring old plug up to 1493')
- 6 Tag plug (should tag at 1493' or less)
- 7 Pull pipe to 834', pump 28sx cmt plug (cover 734'-834') (Yates plug)
- 8 Pull pipe to 686', pump 50sx cmt plug (cover 586'-686') (Base of Salt plug)
- 9 Tag plug (should tag at 586' or less)
- 10 Pull pipe to 320', pump 100sx cmt plug (cover 220'-320') (Top of Salt plug)
- 11 Tag plug (should tag at 220' or less)
- 12 Pull to 60' and pump 45sx surface cmt plug
- 13 Install 4" dry hole marker w/4' above ground w/required info stenciled on pipe

Accepted for record - NMOCD

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Lizabeth Lodig

Title
Engineering Analyst

Signature

Date
February 23, 2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

(ORIG. SGD.) ALEXIS C. SWOBODA

PETROLEUM ENGINEER


APR 1 2002

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**George Atkins - Iles #5**

GL:
KB: 3,655
TD: 1,866
PBD:

Status: D&A
Perls:

API: 30-015-

Fr. Wtr:
Legal: 330 from S
1,850 from E

NM Lse: NML 046119A
Field: High Lonesome (Queen)

Section: 17-O
Township: 16S
Range: 29E
County: Eddy

Logs:

Archeological: none

Casing	Wt	Type	Set	Cmt	Hole	TOC	Method
8 5/8"			446	0	11" est	Csg pulled from hole	
7"			1,593	0	7 7/8" est	Csg pulled from hole	

Sep-54 Spud well
George Atkins (J.C. Clower / agent) - Iles #5

Oct-54 Plug Well

George Atkins - Iles #5 Re-Plugging Procedure

- 1 Remove dry hole marker
- 2 PU 6 3/4" bit, drill out surf plug and 270'-285' plug
- 3 Wash down to cmt plug at 1554'
- 4 Circulate hole w/10ppg mud, POOH
- 5 RIH open ended to 1554' and pump 36sx cmt plug (bring old plug up to 1493')
- 6 Tag plug (should tag at 1493' or less)
- 7 Pull pipe to 834', pump 28sx cmt plug (cover 734'-834') (Yates plug)
- 8 Pull pipe to 686', pump 50sx cmt plug (cover 586'-686') (Base of Salt plug)
- 9 Tag plug (should tag at 586' or less)
- 10 Pull pipe to 320', pump 100sx cmt plug (cover 220'-320') (Top of Salt plug)
- 11 Tag plug (should tag at 220' or less)
- 12 Pull to 60' and pump 45sx surface cmt plug
- 13 Install 4" dry hole marker w/4' above ground w/required info stenciled on pipe