

	20	
	X	

T
16
S

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Field Office Roswell, N.M.

Lease No. N.M. 03361

Unit _____

30-015-02761

R29B

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 12

1955

Brainerd

Well No. 1 is located 660 ft. from [S] line and 1980 ft. from [E] line of sec. 20

SW/4 SE/4

20

163

295

(4 Sec. and Sec. No.)

(Top)

(Range)

(Meridian)

High Lonsome Ext.

Eddy

New Mexico

G.L.

(State or Territory)

The elevation of the derrick floor above sea level is 3616 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show size, weight, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work.)

Drill 10" hole to top of salt. Run 8 5/8" casing and mud off surface water. Drill 8" hole through top of Queen sand and run 7" casing. Mud off water behind 7" casing. Drill 6 1/2" hole through Queen pay section at approximately 1850'. Run 4 1/2" casing to bottom, pull 8 5/8" casing, 7" casing, and circulate cement to surface behind 4 1/2" casing. Perforate pay and complete well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Utex Exploration Company, Inc.

Address Box 886

Artesia, New Mexico

By _____

Title Geologist

