

ACTION TAKEN OR TO BE TAKEN TO PREVENT RECURRENCE: Wellhead was removed and spool with was welded to csg, BOP was re-installed. Well has subsequently been plugged back to surface with BLM oversight.

FINAL INVESTIGATION: \_\_\_\_\_

TEAM NAME(S): \_\_\_\_\_

FIELD INSPECTION DATE: \_\_\_\_\_

SUMMARY OF RESULTS OF INSPECTION \_\_\_\_\_

RESOURCE LOSS WAS (CIRCLE ITEM): \_\_\_\_\_ AVOIDABLE \_\_\_\_ UNAVOIDABLE \_\_\_\_\_

DATE OF MEMO NOTIFYING MINERALS MANAGEMENT SERVICE THAT LOSS WAS UNAVOIDABLE: \_\_\_\_\_

DATE/TIME/PERSON NOTIFIED: \_\_\_\_\_

DISTRICT OFFICE \_\_\_\_\_

STATE OFFICE \_\_\_\_\_

WASHINGTON OFFICE \_\_\_\_\_

SUMMARY OF RESULTS OF RECLAMATION/CORRECTIVE ACTION: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REMARKS: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SIGNATURE OF AUTHORIZED OFFICER: \_\_\_\_\_

DATE: \_\_\_\_\_ TITLE: \_\_\_\_\_