

UNITED STATES N. M. O. C. C. COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
(Other instructions
verse side)TE-
re-Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME FOREST POOL	
2. NAME OF OPERATOR CONTINENTAL OIL COMPANY -		8. FARM OR LEASE NAME FOREST POOL UNIT	
3. ADDRESS OF OPERATOR Box 460, HOBBS, N.M. 88240		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL & 600' FEL OF SEC. 27		10. FIELD AND POOL, OR WILDCAT SQUARE LAKE G-SA	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3664' DF	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 27, T-16S, R-29E	
		12. COUNTY OR PARISH EDDY	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

There are no remaining commercial reserves on this lease. All wells will be plugged; the above named well by the following procedure:

Remove tubing. Run tubing w/cement retainer to set @ 1800'. Squeeze open hole w/300 sks. Class "C" cmt. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer. Pull tubing to 500' & spot 100 sks p/c to slt. Erect Dry Hole marker. No casing will be removed.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]TITLE SR. ANALYSTDATE 12-10-75

(This space for Federal or State office use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APR 15 1976

R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

ARTESIA
USGS-5, Partner, File