

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other Instructio
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.
LC-064832

9. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Marbob Energy Corporation

MAY 22 '89

3. ADDRESS OF OPERATOR
P.O. Drawer 217, Artesia, N.M. 88210

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

ARTESIA, OFFICE

330 FSL 600 FEL

7. UNIT AGREEMENT NAME
Forest Pool Unit

8. FARM OR LEASE NAME
Forest Pool Unit

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Square Lake Grbg SA

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 27-T16S-R29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3664' DF

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to plug & abandon as follows:

Set SV rtmr @ 1890', squeeze w/100 sx cmt; leave 50' cmt on top of SV rtmr. Set 100' plug @ 1300-1200'. Perf csg @ 890' (base salt), try to break circulation, and circulate cmt to surf. If cannot circulate, will perf csg @ 350' and try again. Install dry hole marker and clean location.

RECEIVED
MAY 24 10 29 AM '89

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Clerk

DATE

5/2/89

(This space for Federal or State office use)

APPROVED BY

FOR

TITLE

DATE

5-18-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side