

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. O. C. C. COPY
SUBMIT IN TRIPPLICATE
(Other instructions re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

~~LC 064832~~
C 037777(b)

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ APR 14 1976

2. NAME OF OPERATOR CONTINENTAL OIL COMPANY ✓ D. C. C. ARTESIA, OFFICE

3. ADDRESS OF OPERATOR Box 460, HOBBS, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' ENCL 660' FEL OF SEC. 34

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3664' DF

7. UNIT AGREEMENT NAME FOREST POOL

8. FARM OR LEASE NAME FOREST POOL UNIT

9. WELL NO. 3

10. FIELD AND POOL, OR WILDCAT SQUARE LAKE G-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 34, T-16S, R-29E

12. COUNTY OR PARISH EDDY

13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

There are no remaining commercial reserves on this lease. All wells will be plugged; the above named well by the following procedure:
Remove tubing. Run tubing w/cement retainer to set @ 2475'. Squeeze open hole w/125 sks. Class "C" cmt. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer. Pull tubing to 500' & spot 100 sks plug. Erect Dry Hole marker. (No casing will be removed).

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
APR 18 1976

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

DEC 12 1975

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

DATE 12-10-75

ARTESIA
HOBBS
D. L. HOBBS
FILE