

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved. Copy U.S.I.
Budget Bureau No. 42-R1424.

N. M. D. C. C. DPY

5. LEASE DESIGNATION AND SERIAL NO.

LC 037777(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WATER INJECTION RECEIVED

2. NAME OF OPERATOR CONTINENTAL OIL COMPANY ✓ APR 14 1976

3. ADDRESS OF OPERATOR Box 460, HOBBS, N.M. 88240, C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface ARTERIA, OFFICE
2130' FSL & 660' FEL OF SEC. 34

7. UNIT AGREEMENT NAME FOREST POOL

8. FARM OR LEASE NAME FOREST POOL UNIT

9. WELL NO. 13

10. FIELD AND POOL, OR WILDCAT SQUARE LAKE G-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 34, T-16S, R-29E

12. COUNTY OR PARISH EDDY

13. STATE N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3658' DF (EST.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

There are no remaining commercial reserves on this lease.
All wells will be plugged; the above named well by the following procedure:

Remove tubing. Run tubing w/cement retainer to set @ 2300'. Squeeze open hole w/150 sks. Class "C" cement. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cement above retainer. Pull tubing to 500' & spot 100 sks plug to set. Erect Dry Hole marker.

(No casing will be removed.)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Sr. Analyst

DATE

12-10-75

(This space for Federal or State office use)

APPROVED

TITLE

SIGNATURE OF APPROVAL, IF ANY:

APR 15 1976

H. L. BECKMAN

DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

DEC 12 1975

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOARTESIA
USGS-5, Partner, File