

NM OIL CONS. COMMISSION
Drawer D
ARTESIA, NEW MEXICO
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WATER INJECTION WELL	7. UNIT AGREEMENT NAME FOREST POOL UNIT
2. NAME OF OPERATOR LAYTON ENTERPRISES, INC.	8. FARM OR LEASE NAME FOREST POOL UNIT
3. ADDRESS OF OPERATOR 3103 79th ST LUBBOCK, TEXAS 79423	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL 990' FCL 34 - 165 - 29E	10. FIELD AND POOL, OR WILDCAT SQUAKE LAKE GSA 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 34, 165, 29E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3661 GL
12. COUNTY OR PARISH TERRY	
13. STATE NM.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☒
SHOOT OR ACIDIZE	☐	ABANDON*	☒
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

INTEND TO PLUG & ABANDON WELL AS FOLLOWS:

8 5/8" CASING @ 315' W/ 50 SK CEMENT

7" CASING @ 1909 W/ 100 SK CEMENT

1. CIRCULATE HOLE WITH MOD LADEN FLUID
2. SPOT 250 SK CEMENT PLUG THRU TUBING @ 3600' *
3. PERFORATE 7" CASING, BELOW SALT SECTION, @ 100'
4. PUMP 300 SK CEMENT THRU 7" CASING TERS @ 100' & CIRCULATE TO SURFACE LEAVING 7" COLL
5. SET SURFACE MARKER
6. CLEAR & LEVEL LOCATION

DEC 15 1983

O. C. D.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

Donald C. Layton

TITLE

PRESIDENT

DATE

9-23-83

(This space for Federal or State Use)

APPROVED

(Orig. Sgd.) PETER W. CHESTER

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 14 1983

Tag top of plug to at least 1840'

*See Instructions on Reverse Side