

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLIANCE OR TRIBAL NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR CONTINENTAL Oil Company
3. ADDRESS OF OPERATOR Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 2310' FNL & 1650' FEL OF SEC. 34

APR 14 1976

7. UNIT AGREEMENT NAME

FOREST POOL

8. FARM OR LEASE NAME

FOREST POOL UNIT

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE G-5A

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 34, T-16S, R-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3660' DF

12. COUNTY OR PARISH

13. STATE

EDDY

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

There are no remaining commercial reserves on this lease.
All wells will be plugged; the above named well by the
following procedure:
Remove tubing. Run tubing w/cement retainer to set @
2450'. Squeeze open hole w/175 sks. Class "C" cmt.
Will not reverse out any excess. Pull out retainer & spot
25-50 sks. cmt above retainer.
Pull tubing to 500' & spot 100 sks to stc.
Erect Dry Hole marker.
(No casing will be removed).

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APR 18 1976

R. L. BEEKHUIS

ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side