

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME FOREST POOL
2. NAME OF OPERATOR CONTINENTAL OIL COMPANY	8. FARM OR LEASE NAME FOREST POOL UNIT
3. ADDRESS OF OPERATOR Box 460, HOBBS, N.M. 88240	9. WELL NO. 11
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2120' FSL & 1652' FWL OF SEC. 35	10. FIELD AND POOL, OR WILDCAT SQUARE LAKE G-5A
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3651' DF
	12. COUNTY OR PARISH EDDY
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

There are no remaining commercial reserves on this lease.
All wells will be plugged; the above named well by the following procedure:
Remove tubing. Run tubing w/cement retainer to set @ 2240'. Squeeze open hole w/300 sks. Class "C" cement. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cement above retainer.
Pull tubing to 500' & spot 100 sks plug to set.
Erect Dry Hole marker.
(No casing will be removed.)

I hereby certify that the foregoing is true and correct

SIGNED

TITLE **SR. ANALYST**DATE **12-10-75**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APR 15 1976

J. L. BEEKHUIS

ACTING DISTRICT ENGINEER

TITLE

DATE

RECEIVED

DEC 10 1975

*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOARTESIA
USGS-5, Partner, File