

5. LEASE DESIGNATION AND SERIAL NO. **LC 037777(6)**
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR **CONTINENTAL OIL COMPANY** APR 14 1976

3. ADDRESS OF OPERATOR **Box 460, Hobbs, N.M. 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1980' FNL E 330' FWL OF SEC. 35

7. UNIT AGREEMENT NAME **FOREST POOL**

8. FARM OR LEASE NAME **FOREST POOL UNIT**

9. WELL NO. **9**

10. FIELD AND POOL, OR WILDCAT **SQUARE LAKE G-5A**

11. SEC., T., R., E., M., OR BLK. AND SURVEY OR AREA **SEC. 35 T-16S. R-29E**

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) **3661' DF**

12. COUNTY OR PARISH **EDDY** 13. STATE **N.M.**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

There are no remaining commercial reserves on this lease. All wells will be plugged; the above named well by the following procedure:
Remove tubing. Run tubing w/cement retainer to set @ 2460'. Squeeze open hole w/175 sks. Class "C" cmt. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer. Pull tubing to 500' & spot 100 sks plug to set. Erect Dry Hole marker.
(No casing will be removed.)

I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE SR. ANALYST DATE 12-10-75

(This space for Federal or State office use)

APPROVED **APR 15 1976**
T. C. BEEKWINE
ACTING DISTRICT ENGINEER
ARTESIA
USGS-5, Partner, File

TITLE _____ DATE _____

*See Instructions on Reverse Side

RECEIVED
DEC 12 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO