

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-015-03825

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
E-5131

7. Lease Name or Unit Agreement Name  
EAST HENSHAW UNIT TR. 24

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SALADO OPER. L.L.C.

3. Address of Operator

P.O. BOX 1925 HOBBS, N.M. 88241

4. Well Location

Unit Letter Q : 1980' feet from the SOUTH line and <sup>660'</sup>~~1650'~~ feet from the EAST line

Section 2 Township 16s Range 30e NMPM EDDIE County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3917 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: FINAL REPORT PLUGGING AND ABANDONMENT ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6/15/01 RIGGED UP MAYO MARRS CASING PULLING INC. RIH WITH WORKSTRING AND TAGGED AT 1650'  
CALLED O.C.D. {GERRY GUYE}

6/18/01 TESTED CASING. FULL OF HOLES. RIH AND PERFORATED CASING AT 1638'. RIH WITH TUBING AND SPOTTED 30SX CEMENT 1640'. POOH. W.O.C. RIH AND TAGGED AT 959'. SPOTTED 25SX CEMENT FROM 959' TO SURFACE. ERECTED DRYHOLE MARKER. CLEARED LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Envt. Eng. Spec. I DATE 8/20/01

Type or print name

Telephone No.

(This space for State use)

APPROVED BY [Signature] TITLE Envt. Eng. Spec. I DATE 8/20/01

Conditions of approval, if any:

MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745

NEW MEXICO OCD  
BID ID # 00-521-25-2004

OPERATOR: SALADO OPERATING LLC.

Lease: EAST HENSHAW UNIT 24-1

Project: P & A – CEMENTING REPORT

---

6-18-2001 – TAG TD @ 1640' – PERFORATE @ 1640' PER JERRY GUY

6-18-2001 - SPOT 30 SXS @ 1640'-959' TAGGED

6-18-2001 – SPOT 25 SXS @ 959' - SURFACE

INSTALL DRY HOLE MARKER  
CIRCULATE 10# MUD

4  
JUN 2001  
RECEIVED  
OCD - ARTESIA

MAYO MARRS CASING PULLING INC.  
BOX 863 KERMIT, TEXAS 79745

NEW MEXICO OCD

ATTN: TIM GUM

Lease: E. HENSHAW UNIT TRACT 24-1

OPERATOR: SALADO OPERATING, L.L. C.

Project: P & A

---

6-15-01

MOVE IN RIG UP - LAY DOWN 1 JOINT 1 1/4" IN WELL - RIH WITH WORKSTRING & TAG @ 1640' - CALL OCD - TALK TO JERRY GUY - POOH - CLOSE IN WELL

6-18-01

TEST CASING - FULL OF HOLES - RIH & PERFORATE @ 1638' - RIH WITH TUBING & SPOT 30 SXS @ 1640' - POOH - WOC - RIH 7 TAG @ 959' - POOH & SPOT 25 SXS @ 959' TO SURFACE LEAVING CASING FULL - RIG DOWN - CUT OFF WELLHEAD - INSTALL DRY HOLE MARKER LEVEL LOCATION - MOVE OUT

