

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 11 1972

O. C. C.

NOTICE & OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator <i>Mobil Oil Corporation</i>		5. State Oil & Gas Lease No. <i>OG-779</i>
3. Address of Operator <i>Box 633, Midland, Texas 79201</i>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <i>K</i> <i>4620</i> FEET FROM THE <i>South</i> LINE AND <i>1920</i> FEET FROM THE <i>West</i> LINE, SECTION <i>2</i> TOWNSHIP <i>16-S</i> RANGE <i>30-E</i> NMPM.		8. Farm or Lease Name <i>West Hershaw Premier Unit Tract 13</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>3911 Gr</i>		9. Well No. <i>3</i>
		10. Field and Pool, or Wildcat <i>Hershaw Grayburg West</i>
		12. County <i>Eddy</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandon as Per attached Procedures

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE *Authorized Agent* DATE *12-8-72*

APPROVED BY *[Signature]* TITLE *OIL AND GAS INSPECTOR* DATE *DEC 12 1972*

CONDITIONS OF APPROVAL, IF ANY:

Bottom Plug 720 SX

Notify N.M.O.C.C. in sufficient time to witness

Plugging

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: WEST HERSHAW PREMIER UNIT Well No. TRAT 13.93
Field: WEST HERSHAW
County: EDDY State: NEW MEXICO

RECOMMENDED PROCEDURE:


1. SPOT 100' CEMENT PLUG AT BOTTOM
2. CIRCULATE HOLE TO MUD LADEN FLUID
3. SPOT 1054 PLUG AT SURFACE
4. REMOVE WELL HEAD & INSTALL MARKER.

2A. Cement Plug in 4 1/2" unknown - if possible cut 4 1/2" at 452' ±
and pull - if pulled, spot 100' plug 50' above & 50' below; at
452'

NOTE: VERBALLY APPROVED BY PMOCC OF ARTESIA.

ARA 8/23/72
and 8/23/72

DIAGRAMMATIC WELL SKETCH
 WEST HERSHAW PREMIER UNIT TRACT 13 & 3
 WEST HERSHAW (GRAYBURG) FIELD
 EDDY COUNTY - NEW MEXICO



A.R.A. 8/23/72