

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-069641

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
West Henshaw Unit
Tract 6

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

West Henshaw Grayb

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T-16-S, R30

12. COUNTY OR PARISH

Eddy

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Water Injection AUG 17 '89

2. NAME OF OPERATOR
Penroc Oil Corporation O.C.W.

3. ADDRESS OF OPERATOR
P.O. Box 5970, Hobbs, NM 88241 ARRESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit Letter M, 3300 FSL, 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3863' D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☒

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

August 10, 1989

Rigged up pulling unit. Pulled packer and tubing. Found two bad joints. Ran and set CIBP 100' above the perforations. Displaced hole with 2% KCL water. Layed down all but one joint of tubing. Rigged up Knox Services. Pressured too 500# for 15 min. Test O.K. Layed down one joint of tubing clean location. Rigged. Test witnessed by NMOW.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Penderf

DATE

August 15, 1989

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

PRINTED IN U.S.A.

Revere Oil Corp
West Newbury Framingham MA
Wau 6-1

**CALIBRATED
CHARTS**
SATAMIA, N.Y.

8-10-89

METER NUMBER

TIME PUT ON

DATE PUT ON

TIME TAKEN OFF

DATE TAKEN OFF

BR-2397

BO-2000-8

SIGNS

DAY

NIGHT